


Wiring Diagram



Pin 1 connector SP2110/P9 to Pin 2 RS-422 converter
 Pin 2 connector SP2110/P9 to Pin 1 RS-422 converter
 Pin 3 connector SP2110/P9 to Pin 4 RS-422 converter
 Pin 4 connector SP2110/P9 to Pin 5 RS-422 converter
 Pin 5 connector SP2110/P9 to Pin 3 RS-422 converter



Qty	Description	Item
1	SP2110/P9 , TME, Male contacts	1
1	Converter RS-422 to USB	2
1	Cable FRDR 7x1 300 V CEI 20-22-II	3
1	WH Heat shrink sleeving Ø12, L = 30	4
2	RD Heat shrink sleeving Ø12, L = 30	5

NOTE:

IOLVA www.iolva.it e-mail: iolva.silvano@alice.it		DENOMINAZIONE / Title CAVD RS-422 to USB	
-TUTTE LE QUOTE SONO ESPRESSE IN mm E SI INTENDONO A PEZZI FINITI -Unless otherwise specified, dimensions and tolerances are in mm and after finish. General tolerance: ±		Rotator Elevation	
FIRMA / Signature: _____ DATA / Date: _____ DISEGNATO / Drawn: RICCI 01/2022 APPROVATO / Check: _____		MATERIALE / Material: _____	Trattamento: _____ FINITURA / finish: _____
SCALA / Scale: _____	TAV. / Sheet: _____	REVISIONE: _____	
CODICE / DWG n° 275SA-W001			